Georgia Department of Natural Resources

Environmental Protection Division

Safe Dams Program 4244 International Parkway Suite 110, Atlanta, GA 30354 Noel Hocomb, Commissioner Carol A. Couch, Ph.D., Director 404/362-2678

FILE COPY

March 2, 2005

Mr. Troy Ledbetter Big Canoe Property Owners Association 10586 Big Canoe Big Canoe, GA 30143

SUBJECT:

Lake Petit Dam Pickens County

Dear Mr. Ledbetter:

On January 25, 2005 our staff performed the annual inspection of the subject dam. The following items were noted during the inspection:

- 1. The electric company dug a trench and buried a line through the top of the upper berm. The trench has been compacted and reseeded.
- 2. There is minor wave actions erosion on the upstream slope.
- 3. There is a hole near the large rock on the left side of the top abutment. This hole needs to be backfilled, compacted, and reseeded with a low growing grass such as Bermuda or fescue.
- 4. There are some erosion rills forming on the left abutment on the berm that is second from the top. These rills needs to be backfilled, compacted, and reseeded with a low growing grass such as Bermuda or fescue.
- 5. It is our understanding that you are reading the water level in the piezometers. We need a quarterly report on these readings.
- 6. There is love grass on the dam. The love grass needs to be removed from the dam. This can be completed in steps instead of all at once.
- 7. There is some erosion on the right above the second berm from the bottom. This erosion needs to be backfilled, compacted, and reseeded with a low growing grass such as Bermuda or fescue.
- 8. There is wetness at the lower concrete channel near the road on the left side of the dam. This wetness needs to be monitored for any changes.
- 9. The toe drain channel needs to be cleaned out. The three drains on the right have been damaged. The low-level drain outlet structure and the outlet/toe drain channel need to be cleaned out. The channels should be dug out so that positive drainage can occur.

A copy of the Subsequent Visual Inspection Report is enclosed for your records. If you have any questions, please contact our office at 404/362-2678.

Sincerely,

historile I there

Christopher S. Owen Environmental Engineer III Safe Dams Program

Enclosure

S:\Damdocs\2005 annual inspections\Follow up letters\Owen's letters\01-25-05\Lake Petit Dam - followup.doc