

SUBSEQUENT VISUAL INSPECTION

Date of Inspection 01/25/2005

Name of Dam: Lake Petit Dam County: Pickens

ID#: 112-009-00462 Weather: Sunny and Cold

Inspected by: Chris Owen and Alan Murray

Type of Inspection: Annual Construction Other

Persons Contacted: No one

Toe Drains Right: Did not measure

Toe Drains Left: Did not measure

Additional Drains: Did not measure

Type of Principal Pipe: Concrete

Needs to be Camera Inspected? Maybe Yes No

Low-level drain is being tested? Not Sure Yes No

Comments: They have not tested the low-level drain in years.

Number of Pictures Taken: 4

Remarks: 1) The electric company dug a trench and buried a line through

the top of the upper berm. The trench has been compacted and
reseeded.

2) There is minor erosion on the upstream slope due to waves during the
passing of the hurricanes.

3) There is a hole near the large rock on the left side of the top
abutment.

4) There are some erosion rills forming on the left abutment on the
berm that is second from the top.

5) They are reading the water level in the piezometers.

6) There is love grass on the dam.

7) There is some erosion on the right above the second berm from the
bottom.

8) There is wetness at the lower concrete channel near the road on the
left side of the dam.

9) The toe drain channel needs to be cleaned out. The three drains on

the right have been damaged.

10) The low-level drain outlet structure and the outlet/toe drain

channel needs to be cleaned out.
