

SUBSEQUENT VISUAL INSPECTION

Date of Inspection 01/30/2007

Name of Dam: Petit Lake Dam County: Pickens

ID#: 112-006-00462 Weather: Sunny and Cool

Inspected by: Sree Madichetty and Nancy Prock

Type of Inspection:  Annual  Construction  Other

Persons Contacted: Mike Arp

Toe Drain Right: N/A

Toe Drain Left: N/A

Additional Drains: N/A

Type of Principal Pipe: Corrugated Metal Pipe

Needs to be Camera Inspected?  Maybe  Yes  No

Low-level drain is being tested?  Not Sure  Yes  No

Comments: \_\_\_\_\_

Number of Pictures Taken: \_\_\_\_\_

Remarks:

1. A number of small bare areas were noted on upstream and downstream slope. These should be regrassed with a low-growing grass such as Bermuda or fescue.
2. The two lowest berm toe drains should be cleaned out. The debris is clogging up the drains and causing backup.
3. There is excessive vegetation along the left edge of the downstream slope that should be cleared.
4. You should continue to send quarterly piezometers readings