

JOE D. TANNER Commissioner

Department of Natural Resources

ENVIRONMENTAL PROTECTION DIVISION 270 WASHINGTON STREET, S.W. ATLANTA, GEORGIA 30334

February 14, 1980

J. LEONARD LEDBETTER
Division Director

Mr. J. Craig Cranston, P.E. Baldwin and Cranston Associates, Inc. 1103 Greene Street Augusta, Georgia 30901



Re: Lake Pettit Dam Pickens County

Dear Mr. Cranston,

Pursuant to our conversation on January 31, 1980 on Lake Pettit Dam, the stability of the backslope must be reanalized using the existing 2.0 to 1 backslope in of the design 2.5 to 1 backslope.

Enclosed for your information is a copy of the Phase One Report.

If there are any questions, please feel free to contact our office.

Sincerely,

Francis E. Fiegle, II
Environmental Engineer
Dam Safety Program

FEF:d1 Enclosure cc: Mr. R.A. Gallagher